

Technical Service Bulletin # 3

Product:	Babytherm 8000 OC
Date:	November 30, 1999
Re:	Securing the Radiant Heater RH 600
Reference Doc:	IDM no. 4 / 10.97
Reason:	Unsecured fixing screws of the Radiant Heater RH 600 can loosen during operation. If fixing screws loosen the RH 600 can fall down in worst case.
Solution:	The 4 fixing screws of the Radiant Heater RH600 shall be secured with Loctite 221 in the course of servicing.
Devices affected:	All Babytherm 8000 OC units having Radiant Heater RH600.
When:	At next Service Call or Preventive Maintenance. This action was to be completed by February 28, 1998. Please verify that all units have been modified.
Additional info:	This TSB is identical to TSB RH 600W # 1
Cost:	Covered by Customer, post warranty.
Ordering Info:	79 01 966, screw locking agent, low, Loctite 221
Distribution:	Dräger Service Personnel and Authorized Service Organizations for NCS products.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-723-5935

Dräger Medical, Inc.
Technical Product Manager

Andreas Lenke