



SERVICE BULLETIN

KODAK X-OMAT Processor

Eastman Kodak Company, Health Imaging, Rochester, New York 14650

SERVICE BULLETIN NO. 273

September 1997

3425 KODAK X-OMAT 5000 RA Processor

Version 4.15 Software

Version 4.15 Operating Software is available at no charge from Service Parts Management, Part No. **9B8754**. This software corrects a potential problem with the A/D CONVERTER on the 5000 CIRCUIT BOARD, which can generate an E010 Analog-to-Digital Converter Failure error.

If you are updating the software from Version 2.10, you must adjust the maximum speed potentiometer on the MOTOR CONTROLLER BOARD. Refer to Publication Part No. **8B7484** for the instructions for performing this procedure.

This software should be installed at the next service call or preventive maintenance call. A laptop computer and INTERFACE CABLE, TL-4391 are required to download the software. Please refer to the procedure in the Adjustments and Replacements section of the service manual for instructions on how to download software.

Parts List Corrections

The following parts were either omitted or incorrect in the April 1996 version of the 5000RA Part List, Publication Part No. **5B6345**:

Part No.	Description	Notes	Page Number
779729	SPROCKET DRIVE		4-2, 4-3, 9-8, 10-9
852558	SETSCREW	To mount SPROCKET to SHAFT	4-2, 4-3, 9-8, 10-8
8B7060	RELAY-SOLID STATE-50 Amp	U1,U2,U5	7-8, 7-9, 9-10, 10-6
8B7064	RELAY-SOLID STATE-12 Amp	U3,U4	7-8, 7-9, 9-10, 10-6

Please update your parts list with this information.

Debbie Trubatch
Health Imaging Services

Kodak and X-Omat are trademarks.

7C8283

sb093097_273.doc

Printed in USA

EASTMAN KODAK COMPANY • ROCHESTER, N.Y. 14650

HEALTH IMAGING

