



# SERVICE BULLETIN

## KODAK X-OMAT Processor

Eastman Kodak Company, Health Imaging, Rochester, New York 14650

SERVICE BULLETIN NO. 256

December 1996

**3425 KODAK X-OMAT 5000 RA Processor**  
**3434 KODAK X-OMAT 3000 RA Processor**

**Modification No. 3 for the KODAK X-OMAT 5000 RA Processor**  
**Modification No. 1 for the KODAK X-OMAT 3000 RA Processor**

The above modification is now available from Service Parts Management. It is a Type 1 Required Modification.

The purpose of this modification is to improve reliability of the Processor by replacing the UPPER "A" ROLLER in the FIXER/WASH CROSSOVER with a stainless steel core ROLLER. The original ROLLER (Part No. 467017) could swell and cause the CROSSOVER to bind, resulting in film jams.

In addition, a software download disk (Part No. 9B8449 for the 3000 RA and Part No. 9B8247 for the 5000 RA) with the most recent version operating software (currently 3.31 for the 3000 RA and 3.30 for the 5000 RA) is included. This disk is included for any Processors that have not already been updated to the most recent version. Note that the 5000 and 6000 BOARD BOOT PROM software remains unchanged. The current version is 2.0. It is not necessary to replace these PROMS.

The modification applies to the following serial number ranges:

Processor	Serial Number Range	Mod Kit Part No.
<i>Kodak X-Omat 3000 RA Processor</i>	0 - 3580	9B8376
<i>Kodak X-Omat 5000 RA Processor</i>	0 - 756	9B8377

Dave Green  
Customer Equipment Services

**For More Information:**

**U.S. Distributors Contact:**  
Health Imaging  
Customer Support Operations  
1-800-336-4722

**CES Personnel Contact:**  
Film Handling TAC  
U.S.: 1-800-822-1414  
Canada: 1-800-433-1414  
International: 716-724-4675

*Kodak and X-Omat are trademarks.*

9B8925

sb120396\_256.doc

Printed in USA

EASTMAN KODAK COMPANY • ROCHESTER, N.Y. 14650

**HEALTH IMAGING**

