



SERVICE BULLETIN

KODAK X-OMAT Processor

Eastman Kodak Company, Health Imaging, Rochester, New York 14650

SERVICE BULLETIN NO. 272

September 1997

3058 KODAK X-OMAT Multiloader 300

Modification No. 48 for the Kodak X-Omat Multiloader 300

The possibility exists that RESISTORS of the incorrect value were installed in line with the TWIN WATER VALVE on some *Kodak X-Omat* Multiloader 300s. The value of the RESISTORS installed in line with V1 and V2 of the TWIN WATER VALVE should be 56 ohms ($\pm 10\%$). However, it is possible that an incorrect value RESISTOR was installed during manufacturing. As a result, the COILS of the TWIN WATER VALVE may fail prematurely.

Modification No. 48 for the *Kodak X-Omat* Multiloader 300 is now available from Service Parts Managements as Modification Kit 9226647. The Kit will be available at no charge for a period of 1 year. The Kit includes the following:

Part No.	Description	Qty
9226632	56 ohm RESISTOR	2
MA3058-48	Modification Instructions	1

This is a Type 1 Required Modification. Only Multiloader 300s with the following serial numbers will need to be modified in the field:

- 3212
- 3214 - 3283
- 3285
- 3286

To avoid a possible machine failure, this modification should be installed as soon as possible.

Ralph Lippa
Service Engineer
Health Imaging

For More Information:

U.S. Distributors Contact:

Health Imaging
Customer Support Operations
1-800-336-4722

CES Personnel Contact:

Film Handling TAC
U.S.: 1-800-822-1414
Canada: 1-800-433-1414
International: 716-724-4675

Kodak and X-Omat are trademarks.

7C8282

