



# SERVICE BULLETIN

---

## KODAK X-OMAT Processor

---

Eastman Kodak Company, Health Sciences Division, Imaging Service Center, Rochester, New York 14650

SERVICE BULLETIN NO. 211

January 1995

### *KODAK X-OMAT 180 LP Processor*

#### **Mandatory Mod 5 Available**

The possibility of a short circuit in the Processor exists if processing solutions leak from broken or cracked tank Fittings onto either the EMI Line Filter or Terminal Block TB1. Such damage to the tank Fittings may be caused by over-tightening the Nut on the Fitting.

Modification No. 5 helps to eliminate the potential leaking of processing solutions onto both the EMI Line Filter and Terminal Block TB1. Modification No. 5 provides a new Mounting Bracket and new Cover for the EMI Line Filter and Terminal Block TB1 to replace the existing Cover. The Modification Kit also provides a new Fitting for the developer and fixer Tanks to replace the existing Fitting, Nut, and Washer.

Modification No. 5 is a Type 1, mandatory modification. This Mod **must** be installed on all KODAK X-OMAT 180 LP Processors with Serial No. 1222 and below and on Processors with Serial No. 1232, 1236, 1238, 1239, 1240, 1242, and 1243. The modification must be installed within 4 months of the date of this Service Bulletin. The Modification Kit is now available through Service Parts Management as Part No. 5B6485. Please call **800-431-7278** to order Modification No. 5. Reimbursement instructions for Modification No. 5 are in the Modification Kit. Reimbursement applies to U.S. Dealers and other Service Providers.

**For more information, please contact:**

Eastman Kodak Company  
Health Sciences Division  
Imaging Service Center  
343 State Street, 3rd fl, Bldg 20  
Rochester, NY 14650-1131

(716) 724-1789, Option 1

Please be prepared to give your Customer Service Number and your equipment serial number.

*Kodak and X-Omat are trademarks.*

N-925

