

# MODIFICATION INSTRUCTIONS

for the

## KODAK MULTILOADER 700

Service Code 3053

### Modification No. 11

Type 2

Purpose:

To improve reliability of Film Pocket Motor M7. If MODIFICATION No.11 is not installed  
FILMPOCKET MOTOR TIMOUTS (ELAPSE TIME) might occur.

SERVICE EFFECT:	PCB A4 is modified.
SERIAL NUMBERS:	Up to SN 1356 for 50 Hz units. Up to SN 5143 for 60 Hz units.
INSTALLATION TIME:	approx 1 hour
SPECIAL TOOLS:	none
PARTS REQUIRED:	Capacitor Part No. 4531926 (500 nF)

#### **PLEASE NOTE**

The information contained herein is based on the experience and knowledge relating to the subject matter gained by Kodak prior to publication.

No patent license is granted by this information.

Kodak reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from the use of this information, even if loss or damage is caused by Kodak's negligence or other fault.

- 1.** Open FRONT DOOR.
- 2.** Switch off ML 700.
- 3.** Open left hand COVER.
- 4.** Remove PCB A4.




figure 1

5. Remove and discard CAPACITOR C7.
6. Install new CAPACITOR C7 PN 4531926 (500 nF).




figure 2

7. Circle No. 11 on MOD LABEL.




figure 3

8. Run TEST CYCLES.





**CUSTOMER EQUIPMENT SERVICES KODAK AG STUTTGART GERMANY**