

ML700 Plus MODIFICATIONS

MOD#	TYPE	PART #	DATE	PUB #	SN 50Hz	SN 60Hz	PURPOSE
1	1R	9280406	7/96	MA3443-1	3000 – 3100	7000 – 7075	To avoid a potential safety risk, the FRONT DOOR INTERLOCK ASSEMBLY has to be replaced.
2	1R	9286496	9/97	MA 3053-31	All	All	To avoid corrosion in the COMPRESSOR caused by condensed water flowing back into the COMPRESSOR.