



SERVICE BULLETIN

KODAK Multiloader

Eastman Kodak Company, Health Imaging, Imaging Service Center, Rochester, New York 14650

SERVICE BULLETIN NO. 240

MAY 1996

3053 KODAK MULTILOADER 700 / MULTILOADER 700 Plus

Adjusting the CASSETTE OPENER

This procedure is a replacement for the procedure in the Service Manual for the *Kodak* MULTILOADER 700, Publication No. SM3053.



Important

Check that the OPENER SHOVEL is the correct length. If the OPENER SHOVEL was replaced or the length was changed, do "LENGTH ADJUSTMENT", adjustment 3.18.1, in SM3053, 4/1990.