

Modification Index

Title	Purpose(s)
<p>MODIFICATION INSTRUCTIONS for the <i>Kodak X-Omat 5000 RA PROCESSOR</i> Service Code 3425 Modification No. 1 Type 1 Required</p>	<ul style="list-style-type: none"> • To improve film transport by installing a new FIXER RACK. • To allow cleaning of the CROSSOVERS by installing a new MAIN DRIVE SHAFT, CROSSOVERS, and YOKE. • To provide correct grounding of the REPLENISHMENT PUMPS.
<p>MODIFICATION INSTRUCTIONS for the <i>Kodak X-Omat 5000 RA PROCESSOR</i> Service Code 3425 Modification No. 2 Type 1 Required</p>	<ul style="list-style-type: none"> • To correct the wiring of CIRCUIT BREAKERS 2 and 4. • To modify the DRYER ACCESS PANEL and ELECTRICAL BOX ACCESS PANEL to meet required safety standards.
<p>Type 1 Required MODIFICATION INSTRUCTIONS for Service Codes: 3434 and 3425 <i>Kodak X-Omat 3000 RA PROCESSOR</i> Mod No. 1 <i>Kodak X-Omat 5000 RA PROCESSOR</i> Mod No. 3</p>	<ul style="list-style-type: none"> • To help prevent the possibility of film jams in the FIXER/WASH CROSSOVER, due to swelling of the ROLLER, and to install the latest version of software.
<p>Type 2 MODIFICATION INSTRUCTIONS for the <i>Kodak X-Omat 5000 RA PROCESSOR</i> Mod No. 4</p>	<ul style="list-style-type: none"> • To enable a 5000 RA PROCESSOR to process 30 second processable film